

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2016

Submitted Date:

09/23/2016

Document Number:

682501364

FIELD INSPECTION FORM

Loc ID: 386901 Inspector Name: Trujillo, Aaron On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 36200
 Name of Operator: GRYNBERG* JACK DBA GRYNBERG PETROLEUM CO
 Address: 3600 S. YOSEMITE ST - STE 900
 City: DENVER State: CO Zip: 80237-

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
		r.edelen@grynberg.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447809	WELL	DG			073-06715	Schulte 1-13	CI

General Comment:

This is a construction and stormwater inspection. This inspection covers the additional expansion of the location. Refer to inspection doc. #682501305 for initial construction inspection details. ANY CORRECTIVE ACTIONS FROM PREVIOUS INSPECTION THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.

Location Construction

Location ID: 386901
 Lease Road Adeq.: SATISFACTORY Pads: SATISFACTORY Soil Stockpile: _____ CDP: _____

Comment: Location had been expanded an (approximate) additional 50 feet to the south.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

WADDLES	Yes	Vehicle Trakcing	Yes`
---------	-----	------------------	------

Comments: Erosion BMPs: Stormwater and sediment control BMPs at time of inspection were in proper functioning condition.

Other BMPs:

Corrective Action: _____ Date: _____

SLOPE ROUGHENING	Yes		
------------------	-----	--	--

Comments: Erosion BMPs: Stormwater and sediment control BMPs at time of inspection were in proper functioning condition.

Other BMPs:

Corrective Action: _____ Date: _____

Comment:

Corrective Action: **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 447809 Type: WELL API Number: 073-06715 Status: DG Insp. Status: CI

COGCC Comments

Comment	User	Date
Initial notice of construction for this location was recieved 9/08/2016 stating start date for construction was 9/05/2016. COGCC Rule 316C.c requires that operators shall give at least 48 hours advance written notice of intent to the Commission of a construction or major change at and Well, Oil and Gas Locations, or Oil and Gas Facilities. Notice of intent was given 3 days after construction began, and 7 days after notice was required.	trujilloam	09/23/2016
Notice of construction recieved 9/19/2016 stating construction was to start 9/20/2016. Construction foreman on location stated additional construction had been completed 9/16/2016.	trujilloam	09/23/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682501369	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960247