

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/28/2016

Submitted Date:

09/30/2016

Document Number:

675102966**FIELD INSPECTION FORM**
 Loc ID 398432 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96155Name of Operator: WHITING OIL & GAS CORPORATIONAddress: 1700 BROADWAY STE 2300City: DENVER State: CO Zip: 80290**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
CO, Western	303-876-7091	whitingwesternco@whiting.com	Western slope inspection

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429256	WELL	PR	12/01/2012	OG	103-11931	WRD 23-33R	WK

General Comment:[On location in regards to form 42 notice doc # 401096542](#)

Inspected FacilitiesFacility ID: 429256 Type: WELL API Number: 103-11931 Status: PR Insp. Status: WK**Workover**

Comment: Additional perfs @ 10,600'-10,602' & 10,700'-10,702' - cant pump into. Will run tracer survey to attempt to find tracers. 9 5/8" casing was pressuring up 600/700 psi in a 24 hr period. They decided to drill retainer and cement out and are back to square one with CIBP/retainer at the bottom 11,230' and cement and sand on top and tagged top of cement at 10,995'.

Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675102966	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3965316