

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/07/2016

Submitted Date:

10/03/2016

Document Number:

671000480**FIELD INSPECTION FORM**
 Loc ID 335809 Inspector Name: LUJAN, CARLOS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region
Janicek, Jake		JJanicek@caerusoilandgas.com	EHS
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW
McKee, Michael		MMckee@caerusoilandgas.com	EHS

General Comment:

Environmental Inspection conducted on September 07 to discuss Caerus request to postpone installation of SVE system (see Feb 2016 approved remediation project #9491). On site with Jake Janicek and Michael McKee, from Caerus, and Stan Spencer from the COGCC. A large landslide present immediately up gradient of the pad surface constitutes currently a safety hazard. The COGCC agreed that drilling at this time is not recommended and agreed to re-evaluate the site conditions, early next year, 2017.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
A follow-up inspection will be conducted in early Spring 2017 to observe the landslide conditions and the safety of drilling operations.	lujanc	10/03/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
671000481	Unstable landslide view 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3967115
671000482	Unstable landslide view 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3967116