

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401051463  
Date Received:  
05/20/2016

## FIR RESOLUTION FORM

### CA Summary:

4 of 4 CAs from the FIR responded to on this Form

2 CA Completed  
2 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

[randall.ferguson@pdce.com](mailto:randall.ferguson@pdce.com)

### COGCC INSPECTION SUMMARY:

FIR Document Number: 678800056

Inspection Date: 05/16/2016

FIR Submit Date: 05/17/2016

FIR Status: ACTION REQUIRED

### Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

### LOCATION - Location ID: 323391

Location Name: SHANNON-65N67W Number: 14SENW County: WELD

Qtrqr: SENW Sec: 14 Twp: 5N Range: 67W Meridian: 6

Latitude: 40.401244 Longitude: -104.866355

### FACILITY - API Number: 05-123-00 Facility ID: 245156

Facility Name: SHANNON Number: 14-1

Qtrqr: SENW Sec: 14 Twp: 5N Range: 67W Meridian: 6

Latitude: 40.401335 Longitude: -104.862807

### CORRECTIVE ACTIONS:

1 ☒ CA# 49844

Corrective Action: This Inspection document is for testing of the Field inspection Resolution Form and process. No actual corrective actions were found on this location as documented by this form.

Date: 05/26/2016

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: PDC agrees with the inspection findings. However, the Corrective Action Matrix suggests a proposed corrective action timeframe of 30 days. The FIR allows only 10 days for corrective action. Additionally, the surface owner is currently in the process of crop harvesting and is using that portion of the lease road with heavy equipment. This activity will be completed by May 27, 2016. PDC will then be able to make all needed repairs. Therefore, PDC

respectfully requests additional time to complete the necessary repairs to the access road.

COGCC Decision: Approved

COGCC Representative: date to be changed in FIR please test FIRR after FIR is POSTED

COGCC Supervisor: date to be changed in FIR please test FIRR after FIR is POSTED

**2** ☒ CA# 49845

Corrective Action: This Inspection document is for testing of the Field inspection Resolution Form and process. No actual corrective actions were found on this location as documented by this form.

Date: 05/26/2016

Response: CA COMPLETED

Date of Completion: 05/19/2016

Operator Comment: Removal of surface trash completed. However, the Corrective Action Matrix suggests a proposed corrective action timeframe of 15 days. The FIR allowed only 10 days.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**3** ☒ CA# 49846

Corrective Action: This Inspection document is for testing of the Field inspection Resolution Form and process. No actual corrective actions were found on this location as documented by this form.

Date: 05/26/2016

Response: CA COMPLETED

Date of Completion: 05/19/2016

Operator Comment: Repair of fencing completed. However, the Corrective Action Matrix suggests a proposed corrective action timeframe of 15 days. The FIR allowed 10 days.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**4** ☒ CA# 49847

Corrective Action: This Inspection document is for testing of the Field inspection Resolution Form and process. No actual corrective actions were found on this location as documented by this form.

Date: 05/26/2016

Response: FACTUAL REVIEW REQUEST

Basis for Review: CA dates are not per the guidelines

Operator Comment: PDC's third party stormwater consultant has confirmed the COGCC findings on 5/17/2016. However, the Corrective Action Matrix suggests a proposed corrective action timeframe of 30 days if there is no immediate risk of sediment discharge off the location. The FIR allows only 10 days. The stormwater BMPs in question need minor repairs and there is no immediate risk of offsite discharge of sediment. Also, the subject location is not located proximal to any surface water features. Therefore, PDC respectfully requests additional time for this corrective action.

COGCC Decision: Approved

COGCC Representative: date to be changed in FIR please test FIRR after FIR is POSTED

COGCC Supervisor: date to be changed in FIR please test FIRR after FIR is POSTED

**OPERATOR COMMENT AND SUBMITTAL**

Comment: The corrective action timeframe for all four ACTION REQUIRED issues do not follow the Corrective Action Matrix.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: RANDALL FERGUSON

Signed: \_\_\_\_\_

Title: EHS Compliance Specialist

Date: 5/20/2016 1:24:31 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401051463	FIR RESOLUTION FORM
401051477	Rference Photo
401051503	FIR RESOLUTION SUBMITTED

Total Attach: 3 Files