

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401142560
Date Received:
11/03/2016

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Luke Reddy	970-515-1292	luke.reddy@anadarko.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682401414
Inspection Date: 10/25/2016 FIR Submit Date: 10/31/2016 FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 437948

Location Name: JZM Number: 3N-W3HZ County: _____
Qtrqr: SESW Sec: 10 Twp: 1N Range: 67W Meridian: 6
Latitude: 40.059061 Longitude: -104.880513

FACILITY - API Number: 05-123-00 Facility ID: 437948

Facility Name: JZM Number: 3N-W3HZ
Qtrqr: SESW Sec: 10 Twp: 1N Range: 67W Meridian: 6
Latitude: 40.059061 Longitude: -104.880513

CORRECTIVE ACTIONS:

1 ☒ CA# 53790

Corrective Action: The berm along the southern perimeter of the location is unconsolidated and needs to be compacted to ensure stormwater runoff is directed inside of the BMP. Both culverts installed for the access entrances are currently blocked with fill from the access road. May need to reinstall culverts or redesign access entrance to prevent fill from blocking the culvert. Refer to attached photos in Document #682401416.

Date: 11/11/2016

Response: CA COMPLETED Date of Completion: 11/03/2016

Operator Comment: (1) The berm along the southern perimeter of the location has been compacted to ensure stormwater runoff is directed inside of the BMP.
(2) Both culverts installed for the access entrances have been cleared of any fill and aligned with access to prevent filling/blocking.

Refer to attached photos

COGCC Decision: Approved via an AMI

COGCC
Representative:

Based off attached photo documentation, corrective actions have been performed.

OPERATOR COMMENT AND SUBMITTAL

Comment: (1) The berm along the southern perimeter of the location has been compacted to ensure stormwater runoff is directed inside of the BMP.
(2) Both culverts installed for the access entrances have been cleared of any fill and aligned with access to prevent filling/blocking.
Refer to attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Reddy

Signed: _____

Title: Regulatory Specialist

Date: 11/3/2016 2:01:40 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401142560	FIR RESOLUTION SUBMITTED
401142590	Location Photos

Total Attach: 2 Files