

Well Name Permit #	Receipt #	Receipt #	Status	Use 1	Owner	Certified Mailing	Parcel Data	Mailing Address	City	State	Zip	Phone	Comments
9990-	<a href="http://www">http://www</a>	<a href="http://www">http://www</a>	Well Constructed	Domestic	ROTH HENRY & KATIE	7015 1660 0000 2369 7137 - Sent 8.25.16	NCMC & BH Greeley I LLC	1801 16th St	Greeley	CO	80631		Received letter back 9.8.16. Spoke with Ken ar
78886-F	<a href="http://www">http://www</a>	<a href="http://www">http://www</a>	Well Constructed	Other	WGCC LLC	7015 1660 0000 2369 7144 - sent 8.25.16	WGCC LLC	PO Box 336250	Greeley	CO	80633		Letter received by landowner on 8.29.16. No r
77710-	<a href="http://www">http://www</a>	<a href="http://www">http://www</a>	Permit Expired		CHISMAR JOHN R & JACKIE								
3641-	<a href="http://www">http://www</a>	<a href="http://www">http://www</a>	Well Constructed	Domestic	ELLIOTT BILL	7015 1660 0000 2369 7144 - sent 8.25.16	WGCC LLC	PO Box 336250	Greeley	CO	80633		Letter received by landowner on 8.29.16. No r
3641--A	<a href="http://www">http://www</a>	<a href="http://www">http://www</a>	Well Constructed	Domestic	ELLIOTT D A		Signature Office Park Condo Unit Owners						
14190-R	<a href="http://www">http://www</a>	<a href="http://www">http://www</a>	Well Constructed	Irrigation	ROTHER HENRY	7015 1660 0000 2369 7137 - Sent 8.25.16	NCMC & BH Greeley I LLC	1801 16th St	Greeley	CO	80631		Received letter back 9.8.16. Spoke with Ken ar
70935-	<a href="http://www">http://www</a>	<a href="http://www">http://www</a>	Well Constructed	Domestic	WALKER PAUL	7015 1660 0000 2369 7113 - Sent 8.25.16	Mary J Brighi Trust	1423 71st Street Ave	Greeley	CO	80634		Received letter back 9.2.16. no well on proper
13848-	<a href="http://www">http://www</a>	<a href="http://www">http://www</a>	Well Constructed	Stock	WIEDMAN W N	7015 1660 0000 2369 7120 - Sent 8.25.16	Alan Wiedeman	7611 W 4th Street	Greeley	CO	80634		Letter received by landowner on 8.30.16. No r

nd they do not have a water well that is functioning on the property  
response.

response.

nd they do not have a water well that is functioning on the property  
ty that is functioning  
response.