

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/23/2016
Submitted Date:
11/30/2016
Document Number:
682401548

FIELD INSPECTION FORM

Loc ID 445191 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1625 BROADWAY STE 2200
City: DENVER State: CO Zip: 80202

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445192	WELL	XX	03/18/2016		123-42938	Kramer Federal LC22-725	CI
445193	WELL	XX	03/18/2016		123-42939	Kramer Federal LC22-720	CI

General Comment:

This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401152472. Stormwater and erosion control BMPs need to be installed prior to the start of construction.

Location Construction

Location ID: 445192 CDP: _____

Comment: Stormwater or erosion control BMPs were not installed prior to construction. Operator was informed that BMPs needed to be installed immediately. Prior to leaving the adjacent area, I was informed that temporary BMPs were installed; therefore, no formal corrective action was issued.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
SLOPE ROUGHENING	Yes		

Comments: Erosion BMPs: After calling the operator to install BMPs immediately, surface roughening, which is a temporary BMP, was installed after the start of construction.

Other BMPs: _____

Corrective Action: _____ Date: _____

Comment: Refer to attached inspection photos in Document #682401549

Corrective Action: _____ Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 445192 Type: WELL API Number: 123-42938 Status: XX Insp. Status: CI

Facility ID: 445193 Type: WELL API Number: 123-42939 Status: XX Insp. Status: CI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401549	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016962