

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2016

Submitted Date:

12/02/2016

Document Number:

682401576**FIELD INSPECTION FORM**

Loc ID 439459 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10611Name of Operator: LONGS PEAK RESOURCES LLCAddress: 2323 S SHEPHERD SUITE 1150City: HOUSTON State: TX Zip: 77019**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		egeiser@juncap.com	
		kpeters@juncap.com	
		dclarkson@vrtxep.com	

General Comment:

This is a follow up inspection to FIR Document #682401510- inspection date 11/15/16- to ensure the topsoil stockpile has been stabilized and sediment trap BMPs have been completed.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	In Process					

Comment: Operator was to provide additional communication regarding the stabilization of the topsoil stockpile and completion of sediment control BMPs per verbal agreement on 11/15/16. No such communication has been received and required work has not been performed. Topsoil consists of sandy soils susceptible to wind erosion in this region. As we enter into the winter months, increased precipitation has the potential for increased erosion. BMPs are in place but not completed. Rig has been on location; therefore, BMPs should be completed.

Corrective Action: Two corrective actions shall be performed by 12/16/16:

1) Submit a Form 4 Sundry Notice assigned to Chris Binschus with an attached schedule of planned BMPs to stabilize the topsoil stockpile per Rule 1002.c.

2) Stabilize the western location where soil has been moved from the cut slope and complete the sediment traps by installing a stabilized outlet to prevent sediment laden storm runoff from leaving location.

Date: 12/16/2016

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to attached inspection photos in Document #682401577.	binschusc	12/02/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
682401577	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017507