

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2016

Submitted Date:

11/30/2016

Document Number:

682401548**FIELD INSPECTION FORM**
 Loc ID 445191 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445192	WELL	XX	03/18/2016		123-42938	Kramer Federal LC22-725	CI
445193	WELL	XX	03/18/2016		123-42939	Kramer Federal LC22-720	CI

General Comment:

This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401152472. Stormwater and erosion control BMPs need to be installed prior to the start of construction.

Location Construction

Location ID: 445192 CDP: _____

Comment: Stormwater or erosion control BMPs were not installed prior to construction. Operator was informed that BMPs needed to be installed immediately. Prior to leaving the adjacent area, I was informed that temporary BMPs were installed; therefore, no formal corrective action was issued.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
SLOPE ROUGHENING	Yes		

Comments: Erosion BMPs: After calling the operator to install BMPs immediately, surface roughening, which is a temporary BMP, was installed after the start of construction.

Other BMPs: _____

Corrective Action: _____ Date: _____

Comment: Refer to attached inspection photos in Document #682401549

Corrective
Action: _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 445192 Type: WELL API Number: 123-42938 Status: XX Insp. Status: CIFacility ID: 445193 Type: WELL API Number: 123-42939 Status: XX Insp. Status: CI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401548	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4020740
682401549	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016962