

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2016

Submitted Date:

12/02/2016

Document Number:

682401572

FIELD INSPECTION FORMLoc ID 440192 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**Operator Information:**

OGCC Operator Number: 10611

Name of Operator: LONGS PEAK RESOURCES LLC

Address: 2323 S SHEPHERD SUITE 1150

City: HOUSTON State: TX Zip: 77019

Contact Information:

Contact Name	Phone	Email	Comment
		egeiser@juncap.com	
		kpeters@juncap.com	
		dclarkson@vrtxep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440182	WELL	XX	10/18/2016	LO	123-40719	Pismo East 35-2-2-4CH	CI
440186	WELL	XX	10/18/2016	LO	123-40723	Pismo East 35-2-2-2CH	CI

General Comment:

This is a construction and stormwater inspection in response to Form 42 Document #401147916- Notice of construction of a new location.

Location Construction

Location ID: 440186 CDP: _____

Comment: Topsoil shall be protected from degradation due to contamination, compaction and, to the extent practicable, from wind and water erosion during drilling and production operations. Best management practices to prevent weed establishment and to maintain soil microbial activity shall be implemented. Topsoil stockpile has been stored and separated along the eastern location. Need to stabilize topsoil stockpile from degradation due to wind and water erosion per Rule 1002.c.

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

RETENTION PONDS	Yes		
Comments: Erosion BMPs: Sediment trap installed at northeast corner of location. Sediment trap side slopes should not be steeper than 2:1 and the inlet and outlet should be stabilized. Berms around sediment trap have been stabilized.			
Other BMPs: <div style="border: 1px solid black; height: 20px;"></div>			
Corrective Action: _____		Date: _____	
DITCHES	Yes		
Comments: Erosion BMPs: <div style="border: 1px solid black; height: 20px;"></div>			
Other BMPs: <div style="border: 1px solid black; height: 20px;"></div>			
Corrective Action: _____		Date: _____	
BERMS	Yes		
Comments: Erosion BMPs: Berm shall be compacted to ensure containment of sediment laden storm runoff is directed to the sediment trap.			
Other BMPs: <div style="border: 1px solid black; height: 20px;"></div>			
Corrective Action: _____		Date: _____	
Comment: Refer to attached inspection photos in Document #682401573.			
Corrective Action: <div style="border: 1px solid black; height: 20px;"></div>			Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 440182 Type: WELL API Number: 123-40719 Status: XX Insp. Status: CIFacility ID: 440186 Type: WELL API Number: 123-40723 Status: XX Insp. Status: CI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401572	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017404
682401573	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017326