

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
12/09/2016  
Submitted Date:  
12/11/2016  
Document Number:  
674300797

**FIELD INSPECTION FORM**

Loc ID 322394 Inspector Name: Spencer, Stan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
OGCC Operator Number: 64310  
Name of Operator: NORTHSTAR GAS COMPANY INC  
Address: PO BOX 440789  
City: HOUSTON State: TX Zip: 77244

**Findings:**  
4 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Deranleau, Greg		greg.deranleau@state.co.us	
Nedrow, Ann		ann.nedrow@state.co.us	
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Conklin, Curtis		curtis.conklin@state.co.us	
Lujan, Carlos		carlos.lujan@state.co.us	
McKenny, Ken	(832) 421-4775	kkmacgas@conertric.net	President

**General Comment:**

Site inspection due to a report on 12/8 from Bob Hartman of BLM that wellhead was venting from two valves on east and west side. Contacted the operator, Ken McKenny, via email that "if this release exceeds 1 bbl, COGCC requires a spill report on Form-19 in electronic format within 24 hrs". Mr. McKenny responded that he would have a crew on location on 12/9. He also noted that "all of our wells have been shut-in since early 2016. We are and have been actively trying to sell them. The company does not have any funds of any kind as I explained to the DNR rep i spoke with. I am trying to prevent filing bankruptcy, but if that is our only option, we will have to go that route."

Arrive on location 12/9 am. Weather is 33F and cloudy. Met with BLM staff including: Bob Harman, Jim Byers, Ed Fancher and Carmia Woolley. Operator's cleanup crew does not arrive. Well is still venting both east and west from uncapped valves. Oily mist has blown over steep cutbank (~20' vertical) into Trail Creek onto ice and snow on partially frozen surface. Work with BLM staff to shovel oily snow from creek and bank and deposit in unlined pit south of wellhead. Residual contamination remains impacting soil and vegetation ~100 ft in both directions from wellhead. Difficult to assess volume of spill. Leave site 12:30 pm. Received notice from BLM ~ 3pm that wellhead and been capped and venting stopped. No communication from operator on 12/9.

