

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401166761
Date Received:
12/14/2016

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96340
Name of Operator: WIEPKING-FULLERTON ENERGY LLC
Address: 4600 S DOWNING ST
City: ENGLEWOOD State: CO Zip: 80113
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Linda Boone	(720) 271-8605	ldboonepar@aol.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 673503792
Inspection Date: 10/11/2016 FIR Submit Date: 10/19/2016 FIR Status: _____

Inspected Operator Information:

Company Name: WIEPKING-FULLERTON ENERGY LLC Company Number: 96340
Address: 4600 S DOWNING ST
City: ENGLEWOOD State: CO Zip: 80113

LOCATION - Location ID: 380638

Location Name: WECO-UPRC WILLIAM-613S51W Number: 11SENW County: CHEYENNE
Qtrqtr: SENW Sec: 11 Twp: 13S Range: 51W Meridian: 6
Latitude: 38.932050 Longitude: -103.082420

FACILITY - API Number: 05-017-00 Facility ID: 207759

Facility Name: WECO-UPRC WILLIAM Number: 22-11#2
Qtrqtr: SENW Sec: 11 Twp: 13S Range: 51W Meridian: 6
Latitude: 38.932050 Longitude: -103.082420

CORRECTIVE ACTIONS:

1 ☒ CA# 53558

Corrective Action: Remove piles of debris and weed debris from the location. Decompress soils by cross ripping to a depth of 18 inches. Reseed and reclaim the location. Stabilize the disturbed soil to prevent erosion.

Date: 12/19/2016

Response: CA COMPLETED Date of Completion: 10/31/2016

Operator Comment: Wiepking-Fullerton is submitting this Field Inspection Report Resolution (FIRR) form in response to the Corrective Actions identified in the COGCC inspection conducted on October 11, 2016 (COGCC Doc No. 673503792).

On October 31, 2016, Wiepking-Fullerton performed subsequent reclamation activities. The additional reclamation activities included, removal of debris, soil compaction alleviation by cross ripping the site to a depth

of 18 inches below ground surface, applied Simplot 40-Rock fertilizer at a rate of 50 pounds per acre, seeded the location with NRCS recommended seed mix specific to the location (attached), and crimped in straw at a rate of 2,000 pounds per acre for erosion prevention.

Photos of the reclamation activities were taken on November 22, 2016 (attached).

Wiepking-Fullerton will continue to monitor the site until final reclamation objectives per COGCC Rule 1004 is achieved.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Wiepking-Fullerton is submitting this Field Inspection Report Resolution (FIRR) form in response to the Corrective Actions identified in the COGCC inspection conducted on October 11, 2016 (COGCC Doc No. 673503792).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Linda Boone

Signed: _____

Title: Agent

Date: 12/14/2016 2:09:25 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401166761	FIR RESOLUTION SUBMITTED
401166847	Planted Seed Mix
401166848	Reclamation Site Photos

Total Attach: 3 Files