

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2016

Submitted Date:

12/14/2016

Document Number:

682501486**FIELD INSPECTION FORM**
 Loc ID 376781 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 72085Name of Operator: PETRO-CANADA RESOURCES (USA) INCAddress: 717 17TH STREET #2900City: DENVER State: CO Zip: 80031**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		sherri.robbs@petro-canada.com	
		sherri.robbs@nbleenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202796	WELL	PA	06/02/2000	OW	001-08201	DOWNING B 1	RI

**General Comment:**

This is a follow-up final reclamation and stormwater inspection to inspection doc. #682500936. Any corrective actions from previous inspections that have not been addressed are still applicable. Records show well DA 2013



**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured **Fail**

Compaction alleviation \_\_\_\_\_ Dust and erosion control **Fail**

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: Inspection Doc. #682500936 required operator to re-contour location/access roads and reclaim areas that have not achieved uniform desirable perennial vegetative cover. Location and roads have not been re-contoured/regraded. Inspector was unable to find evidence that unvegetated areas have been seeded. Original corrective actions and corrective action dates remain in place.

Corrective Action:	In accordance to landowner recommendations, re-contour the location at the well pad, and the access road from top of hill to the location, per COGCC reclamation requirements. Bare, unvegetated soil within the fenced area may require additional remediation and seeding to achieve uniform vegetative cover. Remediate soils (where and if needed) until soil meets COGCC 910-1 standards. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the landowner. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.		Date	11/15/2016	
Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>	Multi-Well Location	<input type="checkbox"/>

**COGCC Comments**

Comment	User	Date
Current access road conditions have created a straight, channelized pathway for stormwater. If not reclaimed per COGCC rules, roads will remain at risk of incision and degradation.	trujilloam	12/14/2016
Following comment taken from Inspection Doc. 682500936	trujilloam	12/14/2016
Documented areas within the fenced area of the location remain unvegetated. Pit and well file documents state location underwent remediation for soils impacted by produced water. Figure 2 in the attached document show large, unvegetated areas within the fenced areas.		
Based on this information, the bare, unvegetated areas within the fenced area are likely due to salt kill from produced water.		
Access road and location have not been re-contoured per reclamation requirements; slopes, ruts and depressions remain evident.		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682501486	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027516">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027516</a>
682501487	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027387">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027387</a>