



STATE OF  
COLORADO

Andrews - DNR, Dave <david.andrews@state.co.us>



## follow up on lost circulation

Andrews - DNR, Dave <david.andrews@state.co.us>  
To: Hans Wychgram <hwychgram@ursaresources.com>

Fri, Jun 17, 2016 at 9:23 AM

Thanks, Hans. No further action required.

Dave

David D. Andrews, P.E., P.G.  
Engineering Supervisor - Western Region



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

P 970.625.2497 x1 | F 970.625.5682 | C 970.456.5262  
796 Megan Avenue, Suite 201, Rifle, CO 81650  
david.andrews@state.co.us | www.colorado.gov/cogcc

On Fri, Jun 17, 2016 at 8:48 AM, Hans Wychgram <hwychgram@ursaresources.com> wrote:

Dave,

This message is in regard to our lost circulation event that took place Wednesday morning. Here's the info from the Form 42 that we filed:

Well name:	Tompkins 41C-08-07-95
API #:	050452248100
Date:	06/15/16
Time:	9:15am
Depth:	638'
Total volume of mud lost:	350 bbls

As we discussed, we spent some time inspecting the low areas around the pad yesterday. We found nothing out of the ordinary. In addition, we pulled a sample from one of our monitoring wells and all looked normal. We did finish drilling the surface section for this well, and ran and cemented surface casing with no issues. The cement job was a text book job for us, and we got good cement to surface.

Please let me know if you need any additional follow up.

6/24/2016

State.co.us Executive Branch Mail - follow up on lost circulation

Thanks,

Hans