

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
12/09/2016  
Submitted Date:  
12/22/2016  
Document Number:  
680601185

**FIELD INSPECTION FORM**

Loc ID 325906 Inspector Name: ROY, CATHERINE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

**Findings:**  
6 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre		Sabre.Beebe@bp.com	<a href="#">All Inspections</a>
,		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215547	WELL	PR	12/01/1988	GW	067-07152	FEINBERG C 1	RI

**General Comment:**  
[This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.](#)

**Inspected Facilities**

Facility ID: 215547 Type: WELL API Number: 067-07152 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by ponderosa pine forest. Revegetation is progressing within the interim reclamation areas. See attached photos.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment

Corrective Action

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_



<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Stormwater erosion is occurring in the northwestern portion of the project area where stormwater flows off of the flat well pad surface. Rilling is also occurring on well pad cut-slopes in the eastern portion of the project area.</p> <p>Corrective Action: Stormwater controls need to be installed to stabilize erosion in the northwestern portion of the project area. Erosion on the eastern fill slope needs to be evaluated when snow is no longer present and controls installed if needed. Extended corrective action date is to accomodate snow and frozen soils.</p>						Date: 05/01/2017
<p><b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

<b>COGCC Comments</b>		
Comment	User	Date
Stormwater erosion needs to be repaired by May 1, 2017.	RoyC	12/22/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680601185	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4036036">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4036036</a>
680601186	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4036024">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4036024</a>