



Photo#1: There is no evidence of the AL Wells on this Active Location.

January 10, 2017

Inspection Photos: Encana BJM Loc#334840 ALs



Photo#2: There is no evidence of the AL Wells on this Active Location with Three PR Wells.

Inspection Photos: Encana BJM Loc#334840 ALs

January 10, 2017