



KOCH EXPLORATION COMPANY, LLC

---

January 13, 2017

Colorado Oil & Gas Conservation Commission  
Mr. Craig Burger  
Northwest Engineer  
[craig.burger@state.co.us](mailto:craig.burger@state.co.us)

1120 Lincoln Street, Suite 801  
Denver, CO 80203

WARNING LETTER # 401183850  
WRD FEDERAL 2-23 (API# 103-10988)  
NWSE, 23, 2N, 97W, RIO BLANCO

Mr. Burger,

Koch Exploration Company has reviewed the circumstances around the casing repair work done on the WRD FEDERAL 2-23 well. We have reviewed and updated our procedures for commencing well work, including identifying the types of well interventions that require prior approval from regulatory authorities, and we have trained our staff on those procedures. We are comfortable that the updated procedures will prevent recurrence of this alleged violation.

Sincerely,

A handwritten signature in blue ink, appearing to read 'D. Howard'.

Douglas Howard  
VP Operations  
Koch Exploration Company, LLC  
(303) 325-2562  
[howard4d@kochind.com](mailto:howard4d@kochind.com)