



OUTCOME NOTICE for WARNING LETTER # 401158617

01/24/2017

NOBLE ENERGY INC (# 100322)

Scott Park

scott.park@nblenergy.com

1625 BROADWAY STE 2200

DENVER, CO 80202

Re: Warning Letter # 401158617

Date Issued 12/06/2016

BALL RANCH AC15-04 (API# 123-34890)

NWNW, 15, 7N, 63W, WELD

This Outcome Notice is to inform you of the status of the violation(s) alleged in the above referenced Warning Letter.

Alleged Violation(s) and Required Corrective Action(s):

317.p Requirement to Log Well

Description of Alleged Violation: Pursuant to Rule 317.p., for all new drilling operations, Noble Energy Inc (Operator) is required to run a resistivity log with gamma-ray that adequately describe the stratigraphy of the wellbore. Operator spud the Ball Range AC 15-04 well, API 123-34890, (Well) on March 15, 2012, and submitted a Form 5, Final Drilling Completion Report, on March 26, 2013 (Document #400395561), but did not include an open hole resistivity log with gamma-ray, as required by Rule 308A. Based on information available through COGCC records, it appears that no resistivity log with gamma-ray was run for the Well, violating Rule 317.p.

Required Corrective Action: Operator shall submit a Form 4, Sundry Notice, that provides all additional logs run for the Well, provides a core analysis, and details the procedures Operator will employ in the future to ensure that open hole logging will occur as required by Rule 317.p.

Corrective Action Deadline Date: 01/06/2017

Corrective Action Performed by Operator

Description: Operator submitted the requested Form 4, Sundry Notice, that provides all additional logs run for the Well, provides a core analysis, and details the procedures Operator will employ in the future to ensure that open hole logging will occur as required by Rule 317.p.

Completion Date: 12/20/2016

Outcome of Warning Letter # 401158617: No Further Action Required





Operator submitted the requested Form 4, Sundry Notice, that provides all additional logs run for the Well, provides a core analysis, and details the procedures Operator will employ in the future to ensure that open hole logging will occur as required by Rule 317.p.

Other Violations:

If COGCC has reasonable cause to believe that NOBLE ENERGY INC has additional violations not addressed through the above referenced Warning Letter, the COGCC may issue a Notice of Alleged Violation and seek penalties pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. COGCC may or may not elect to issue Warning Letters for additional instances of non-compliance based on the guidance of the COGCC Enforcement Guidance and Penalty Policy (Corrected 4/8/2015) and COGCC Rules.

Sincerely,

Barbara Westerdale
Permit/Completion Supervi
(303)894-2100x5159
barbara.westerdale@state.co.us

Attachments

View Attachments in Imaged Documents on COGCC website <http://ogccweblink.state.co.us/> Search by Document Number.

Document Number **Description**

401158617	WARNING LETTER OUTCOME NOTICE
401161560	WARNING LETTER CERTIFIED MAIL RECEIPT
401161574	WARNING LETTER ISSUED
401161636	WARNING LETTER IN PROCESS

Total Attach: 4 Files

