

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401190332
Date Received:
01/20/2017

FIR RESOLUTION FORM

CA Summary:
1 of 1 CAs from the FIR responded to on this Form
1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1625 BROADWAY STE 2200
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name: owen williams
Phone: 970-304-5000
Email: owen.williams@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682401640
Inspection Date: 12/13/2016 FIR Submit Date: 12/23/2016 FIR Status:

Inspected Operator Information:

Company Name: NOBLE ENERGY INC Company Number: 100322
Address: 1625 BROADWAY STE 2200
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 445234

Location Name: LC24-03 Number: PAD County:
Qtrqr: NENW Sec: 24 Twp: 9N Range: 59W Meridian: 6
Latitude: 40.741270 Longitude: -103.929120

FACILITY - API Number: 05-123-00 Facility ID: 445234

Facility Name: LC24-03 Number: PAD
Qtrqr: NENW Sec: 24 Twp: 9N Range: 59W Meridian: 6
Latitude: 40.741270 Longitude: -103.929120

CORRECTIVE ACTIONS:

1 CA# 54718

Corrective Action: Perform one of the two corrective actions:
1) Provide construction calculations from the site specific stormwater plan demonstrating that the installed BMPs described above are sufficient to prevent sediment laden storm runoff from leaving location
or,
2) Install sufficient BMPs in accordance with good engineering practices per Rule 1002.f.

Date: 01/20/2017

Response: CA COMPLETED Date of Completion: 01/20/2017

Operator Comment: Diversion ditches and sediment traps were installed on 12/1/2016. Sediment traps are installed at the outlet of diversion ditches to allow sediment to settle out of stormwater runoff and used for drainage areas less than ten acres. Multiple sediment traps have been installed on location, estimated disturbance area of 5.4 acres

COGCC Decision: **Not Approved**

COGCC Representative: This response does not address the Corrective Action to demonstrate that the installed BMPs are sufficient. Corrective Action still remains open.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Owen Williams Signed:

Title: Sr. EHS Coordinator Date: 1/20/2017 2:06:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401190332	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files