

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401190178
Date Received:
01/20/2017

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name

Phone

Email

owen williams

970-304-5000

owen.williams@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682401638

Inspection Date: 12/13/2016

FIR Submit Date: 12/23/2016

FIR Status:

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 445232

Location Name: LC24-02 Number: PAD County:

Qtrqtr: NWNE Sec: 24 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.741260 Longitude: -103.923440

FACILITY - API Number: 05-123-00 Facility ID: 445232

Facility Name: LC24-02 Number: PAD

Qtrqtr: NWNE Sec: 24 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.741260 Longitude: -103.923440

CORRECTIVE ACTIONS:

1 CA# 54716

Corrective Action: Remove waste material from location per Rule 603.f.

Date: 01/06/2017

Response: CA COMPLETED

Date of Completion: 12/20/2016

Operator Comment: Waste material removed from location.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: _____

2  CA# 54717

Corrective Action: Stabilize western cut slope to prevent erosion per Rule 1002.f. In addition, perform one of the two corrective actions:

Date: 01/20/2017

1) Provide construction calculations from the site specific stormwater plan demonstrating that the installed BMPs described above are sufficient to prevent sediment laden storm runoff from leaving location

or,

2) Install sufficient BMPs in accordance with good engineering practices per Rule 1002.f.

Response: CA COMPLETED

Date of Completion: 01/10/2017

Operator Comment: Cut slope has hydromulch applied to stabilize. Any erosion occurring on the cut slope will occur from stormwater running onto the disturbed area and sediment will be contain on location.

COGCC Decision: **Not Approved**

COGCC Representative: 1) Corrective Action to stabilize the western cut slope is approved pending re-inspection.
2) Operator failed to respond to the following Corrective Action that will remain open.

Perform one of the two corrective actions:

Provide construction calculations from the site specific stormwater plan demonstrating that the installed BMPs described above are sufficient to prevent sediment laden storm runoff from leaving location

or,

Install sufficient BMPs in accordance with good engineering practices per Rule 1002.f.

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Owen Williams

Signed: _____

Title: SR. EHS Coordinator

Date: 1/20/2017 1:10:02 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401190178	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files