

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2017

Submitted Date:

01/20/2017

Document Number:

682501626**FIELD INSPECTION FORM**
 Loc ID 436726 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Strickler, Robert		Robert.D.Strickler@conocophillips.com	All Inspections DJ Basin
Carlile, Justin	(281) 206-5770	justin.carlile@conocophillips.com	
Binschus, Chris		chris.binschus@state.co.us	
Gahr, Dean	(303) 268-3723	Dean.P.Gahr@conocophillips.com	All Inspections DJ Basin

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436725	WELL	PR	10/27/2014	OW	001-09805	Reserve 3-65 34-35 1H	RI

**General Comment:**

This is an interim reclamation and stormwater inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Inspected Facilities									
Facility ID:	436725	Type:	WELL	API Number:	001-09805	Status:	PR	Insp. Status:	RI
Producing Well									
Comment:	PR, IR inspection								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: DRY LAND

Comment: [Interim areas have not been returned to cropland.](#)**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ Fail \_\_\_\_\_

Comment [Top soil berm on the south end of the location predominantly vegetated with undesirable weedy plant species such as kochia and russian thistle, or is exposed soil. See figure 4 in the attached photo document.](#)

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? Fail Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced Fail Recontoured Fail Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

## 1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

This location does not meet reclamation requirements. The western portion of the project area does not appear to be necessary for production activities. See figures 7-11. This area needs to be reclaimed per the 1003 reclamation rules. Reclamation rules require locations to be reclaimed to their original condition or final land use. 2A doc. #400541902 states current and final land use designation as "dry land" cropland. Interim reclamation has not been performed; areas not reasonably needed for production operations have not been returned to their original condition or final land use (crop land). See attached photo document.

Corrective Action

Perform interim reclamation on all areas not reasonably needed for production operations in accordance to reclamation rules. Reclaim interim areas to their original condition or final land use.

Date 04/15/2017Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: DRY LAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_

Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

## VEGETATIVE COVER \_\_\_\_\_

Comment: Corrective Action: 

Date \_\_\_\_\_

Overall Final Reclamation

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Pass	Rip Rap	Pass			
Waddles	Fail					See Below
Ditches	Pass	Culverts	Pass			

Comment: Wattles used for stormwater and sediment control BMPs along perimeter of location are in disrepair and no longer in proper functioning condition. Refer to figures 5, 12 and 14 in the attached photo document.

Corrective Action: Install or repair required BMPs per rule 1002.f. Refer to guidance document for further details.

Date: 04/15/2017

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Reclamation rule 1003.b requires that interim reclamation shall occur no later than three (3) months on crop land. 2A Doc. #400541902 states that current and future land use is "dry land cropland". Well logs show production records beginning September of 2014. Interim reclamation should have commenced no later than December 2014. Sundry Doc. #400923162 received 10/22/2015 stated interim reclamation "will commence approximately 10/27/2015". This is 10 months after COGCC reclamation rules required reclamation to commence on croplands.	trujilloam	01/20/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401190030	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055977">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055977</a>
682501627	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055976">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055976</a>