

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
02/06/2017
Submitted Date:
02/06/2017
Document Number:
667600120

FIELD INSPECTION FORM

Loc ID 320217 Inspector Name: Kraich, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 90615
Name of Operator: TUDEX PETROLEUM INC
Address: UNIT E 2121 39TH AVENUE NE
City: CALGARY State: AB Zip: T2E 6R7

Findings:
17 Number of Comments
6 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Reeve, Robert	360-683-3385	rrobert169@qwest.net	Engineer
Conn, Lionel	1 40 3250 7225	tudorcorp@hotmail.ca	President
MCCLANE, GENE		genemcclane@hotmail.com	All inspections
Rutter, Jenn		JRutter@adcogov.com	Unincrop. Adams County Inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203084	WELL	PR	12/01/2014	OW	001-08491	LAMBERT 2	WK

General Comment:
Spoke with Gene McClane on workover loction, he is currently in process of taking ownership of well and location from Tudex.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign reflects Tudex		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Signage at battery lacks emergency contact information.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	No emergency contact information posted at battery.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 03/07/2014

Good Housekeeping:			
Type			
Comment:	No trash and debris as indicated by previous inspection.		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
PW/CO	Separator	<= 1 bbl	
Comment:	Stained soil below fire tube at separator. See attached photos.		
Corrective Action:	Remove or remediate stained soil.		Date: 03/06/2017

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	Paint on separator is not proper coloring.		
Corrective Action:	Paint separator per Rule 804.		Date: 07/01/2017
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		

Comment: Gas fired engine.		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:	Tank paint in not proper coloring. See attached photos.				
Corrective Action:	Paint tanks per Rule 804.				Date: 07/01/2017

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	A animal burrow south east corner of tank berm. See attached photos.			
Corrective Action:	Repair berms or other secondary containment devices per Rule 906.d.(1).			Date: 03/06/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	Open Top		
Comment:	Fiberglass open top, netting needs repaired, see attached photos.				
Corrective Action:	Repair netting to mitigate possible wildlife entry.				Date: 04/06/2017

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms


Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Same berms as oil tank.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:



Inspected FacilitiesFacility ID: 203084 Type: WELL API Number: 001-08491 Status: PR Insp. Status: WK**Workover**Comment: Matco rig in process of well maintenance.Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
667600138	H2O Tank Netting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069081
667600139	Hole in Berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069082
667600141	Separator Fire Tube	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069083
667600142	Separator Paint	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069084
667600143	Tank Paint	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069085