

15690 E 33rd Ave., Unit A, Aurora CO 80011-1322
 Ph. 800.540.7967 Western Slope: 970.812.2293
www.summitservicesgroup.com

O 29-596 LANDFARM PLAN Overview Map




Drafted by: B.J.Russell

Date: 5/27/2016






2' BUFFER TO BE MAINTAINED BETWEEN
LANDFARM MATERIAL AND EARTHEN
CONTAINMENT BERM FOR ADEQUATE
STORMWATER FREEBOARD



LANDFARM MATERIAL WILL BE
CONTAINED BY A 2' HIGH COMPACTED
EARTHEN BERM CONSTRUCTED FROM
NON-CONTAMINATED SOILS (See figure
B-1 on pg. 3 for construction details)

AREA WHERE LANDFARM MATERIAL WAS
REMOVED WILL BE RE-CONTOURED,
SURFACE ROUGHENED, SEEDED, AND
MULCHED TO PREVENT EROSION

EXISTING
LATHAM 029 PAD

	LANDFARM MATERIAL	Legend
	2' HIGH COMPACTED EARTHEN BERM	
	RECONTOUR/SEED/MULCH	

O 29-596 LANDFARM PLAN LANDFARM PLAN



**Figure B-1
Berm Installation**

