

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401203626

Date Received:

02/07/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

SanJuanCOGCC@bp.com

Beebe, Sabre

970-375-7530

Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685301997

Inspection Date: 12/20/2016

FIR Submit Date: 12/20/2016

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 333707

Location Name: LEMON GAS UNIT J-M34N8W Number: 17NWSE County: LA PLATA

Qtrqtr: NWSE Sec: 17 Twp: 34N Range: 8W Meridian: M

Latitude: 37.188647 Longitude: -107.739895

FACILITY - API Number: 05-067- -00 Facility ID: 258267

Facility Name: LEMON J Number: 2

Qtrqtr: NWSE Sec: 17 Twp: 34N Range: 8W Meridian: M

Latitude: 37.188647 Longitude: -107.739895

CORRECTIVE ACTIONS:

1 CA# 54664

Corrective Action: Install sign to comply with Rule 210.b

Date: 02/19/2017

Response: CA COMPLETED

Date of Completion: 02/01/2017

Operator Comment: New signs have been placed on location.

COGCC Decision: _____

COGCC Representative:	
-----------------------	--

2	CA# 54665	Corrective Action: Remove or install parts to comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date: <u>01/20/2017</u>
Response: <u>CA COMPLETED</u>		Date of Completion: <u>01/25/2017</u>	
Operator Comment:		Corrective Action previously closed with FIRR form 401193265 see attached.	
COGCC Decision: _____			
COGCC Representative:			

3	CA# 54666	Corrective Action: Repair or install required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.	Date: <u>01/20/2017</u>
Response: <u>CA COMPLETED</u>		Date of Completion: <u>01/25/2017</u>	
Operator Comment:		Corrective Action previously closed with FIRR form 401193265 see attached.	
COGCC Decision: _____			
COGCC Representative:			

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	New signs have been placed on location for all wells. Old signs require a truck with lift capabilities due to weight of base so these will be removed when the heavy duty truck with lift is available.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: <u>Sabre Beebe</u>	Signed: _____
Title: <u>Compliance Specialist</u>	Date: <u>2/7/2017 8:30:29 AM</u>

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401203644	FIRR document for previous closed DA
401203645	Sign CA documentation

Total Attach: 2 Files