

STATE OF
COLORADO

Gintautas - DN

received 02/06/2017
REM 8307
Document 2527623

s>

FW: Homestead Oil - Stephens #1, Remediation #8307

1 message

Paul Henehan <paulh@fremontenv.com>

Mon, Feb 6, 2017 at 6:04 PM

To: "Gintautas - DNR, Peter" <peter.gintautas@state.co.us>

Hi Peter – on behalf of our client, Homestead Oil, please see the attached Ground Water Data Submittal for the Stephens #1 in Weld County.

As indicated in this document, the benzene concentrations in wells MW-1 and MW-5 have rebounded somewhat; as a result, Homestead has requested that the AS/SVE system be re-activated at the site for approximately three months.

We have a couple of issues to iron out with Xcel Power to re-activate the electrical service at this location. When that is resolved, we'll restart the remediation system.

If we can answer any questions regarding this site, please let me know.

Best regards,

Paul V. Henehan, PE

Fremont Environmental Inc.

1759 Redwing Lane

Broomfield, CO 80020

(303) 956-8714 (direct/cell)

**Stephens GW Data Submittal Feb 2017.pdf**

1916K