

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401139369

Date Received:

10/31/2016

## FIR RESOLUTION FORM

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Labowskie, Steve

steve.labowskie@state.co.us

Inspections, All

SanJuanCOGCC@bp.com

Beebe, Sabre

970-375-7530

Sabre.Beebe@bp.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 685301458

Inspection Date: 09/20/2016

FIR Submit Date: 09/22/2016

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 326656

Location Name: TILLMAN BURCH GAS UNIT- N33N8W Number: 12SENE County: LA PLATA

Qtrqtr: SENE Sec: 12 Twp: 33N Range: 8W Meridian: N

Latitude: 37.122253 Longitude: -107.663255

### FACILITY - API Number: 05-067- -00 Facility ID: 261488

Facility Name: TILLMAN BURCH Number: 2

Qtrqtr: SENE Sec: 12 Twp: 33N Range: 8W Meridian: N

Latitude: 37.122253 Longitude: -107.663255

### CORRECTIVE ACTIONS:

1 ☒ CA# 53020

Corrective Action: Clean up and remediate stained soil to comply with Rule 906.a.

Date: 10/26/2016

Response: CA COMPLETED

Date of Completion: 10/10/2016

Operator Comment: Stained soils cleaned up and remediated per Rule 906.a.

COGCC Decision: Approved

COGCC Representative: Follow Up Inspection completed on 12/13/2016. Corrective action complete. See Inspection Report document number 685301971 for additional details.

2 ☒ CA# 53021

Corrective Action: Install or repair BMPs to comply with Rule 1002.f. Refer to 1002.f guidance document for further details.

Date: 10/26/2016

Response: CA COMPLETED

Date of Completion: 10/10/2016

Operator Comment: Old wattles removed and new wattles placed to comply with Rule 1002.f. see attached action document

COGCC Decision: Approved

COGCC Representative: Follow Up Inspection completed on 12/13/2016. Corrective action complete. See Inspection Report document number 685301971 for additional details.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 10/31/2016 7:31:32 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401139369	FIR RESOLUTION SUBMITTED
401139376	Photos of BMP replacement

Total Attach: 2 Files