

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401143425
Date Received:
11/04/2016

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 26625
Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC
Address: 12225 GREENVILLE AVE STE 950
City: DALLAS State: TX Zip: 75243-9362
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

| Contact Name | Phone | Email |
|-----------------|----------------------|-------------------------|
| Archuleta, Amy | | aarchuleta@elmridge.net |
| Lindeman, Terry | 505-632-8048 EXT 210 | tlindeman@elmridge.net |

COGCC INSPECTION SUMMARY:

FIR Document Number: 685301544
Inspection Date: 10/11/2016 FIR Submit Date: 10/12/2016 FIR Status:

Inspected Operator Information:

Company Name: ELM RIDGE EXPLORATION COMPANY LLC Company Number: 26625
Address: 12225 GREENVILLE AVE STE 950
City: DALLAS State: TX Zip: 75243-9362

LOCATION - Location ID: 333415

Location Name: IGS Number: 156 County: LA PLATA
Qtrqr: NWN Sec: 26 Twp: 33N Range: 9W Meridian: N
Latitude: 37.078970 Longitude: -107.801080

FACILITY - API Number: 05-067-00 Facility ID: 256491

Facility Name: DAVIS FR Number: 1
Qtrqr: NWN Sec: 26 Twp: 33N Range: 9W Meridian: N
Latitude: 37.078970 Longitude: -107.801080

CORRECTIVE ACTIONS:

1 ☒ CA# 53402

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).
Repair or install berms or other secondary containment device to comply with Rule 605.a.(4).

Date: 11/11/2016

Response: CA COMPLETED Date of Completion: 11/04/2016

The berm has been repaired on this location.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow up Inspection will be conducted on location before 10/11/2017.

2 ☒ CA# 53403

Corrective Action: Maintain access road to comply with Rule 604.c.(2).S

Date: 11/11/2016

Response: CA COMPLETED

Date of Completion: 11/04/2016

Operator
Comment: The access road has been fixed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow up Inspection will be conducted on location before 10/11/17.

3 ☒ CA# 53404

Corrective Action: Repair or install required BMPs to comply with Rule 1002.f.

Date: 11/11/2016

Response: CA COMPLETED

Date of Completion: 11/04/2016

Operator
Comment: BMPs have been installed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow up Inspection will be conducted before 10/11/2017.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amy

Signed: _____

Title: Archuleta

Date: 11/4/2016 12:38:11 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------------|
| 401143425 | FIR RESOLUTION SUBMITTED |
| 401143426 | Photos |

Total Attach: 2 Files