

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401143760  
Date Received:  
11/07/2016

## FIR RESOLUTION FORM

### CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) Fax: ( )  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Beebe, Sabre</u>	<u>970-375-7530</u>	<u>Sabre.Beebe@bp.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 685301614  
Inspection Date: 10/17/2016 FIR Submit Date: 10/19/2016 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 325847

Location Name: STREETER FEDERAL GAS UNIT-N35N7W Number: 28SESE County: LA PLATA  
Qtrqr: SESE Sec: 28 Twp: 35N Range: 7W Meridian: N  
Latitude: 37.268217 Longitude: -107.636476

### FACILITY - API Number: 05-067- -00 Facility ID: 215466

Facility Name: STREETER FEDERAL Number: 1  
Qtrqr: SESE Sec: 28 Twp: 35N Range: 7W Meridian: N  
Latitude: 37.268217 Longitude: -107.636476

### CORRECTIVE ACTIONS:

3 ☒ CA# 53551

Corrective Action: Remove debris to comply with Rule 603.f using the Rule 603.f guidance document for additional details.

Date: 11/21/2016

Response: CA COMPLETED

Date of Completion: 11/03/2016

Operator Comment: Wood cutting debris cleaned up and disposed of.

COGCC Decision: Approved

COGCC Representative: Follow Up Inspection completed on 1/10/2017. Corrective action complete. See Inspection Report document number 685302098 for additional details.

4 ☒ CA# 53552

Corrective Action: Repair or install required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 11/21/2016

Response: CA COMPLETED

Date of Completion: 11/03/2016

Operator Comment: See attached closure document showing work completed on BMP's

COGCC Decision: Approved

COGCC Representative: Follow Up Inspection completed on 1/10/2017. Corrective action complete. See Inspection Report document number 685302098 for additional details.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 11/7/2016 7:42:54 AM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401143760	FIR RESOLUTION SUBMITTED
401143761	BMP repair closure document

Total Attach: 2 Files