

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401165199

Date Received:

12/12/2016

FIR RESOLUTION FORM

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10343

Name of Operator: QEP ENERGY COMPANY

Address: 1050 17TH STREET - SUITE 800

City: DENVER State: CO Zip: 80265

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Abrams, Laura</u>	<u>303-260-6745</u>	<u>laura.abrams@qepres.com</u>
<u>Tomkinson, Stephanie</u>	<u>435-781-4308</u>	<u>stephanie.tomkinson@qepres.com</u>
<u>Maez, Leonard</u>	<u>(970) 564-1699/(806) 435-0529</u>	<u>leonard.maez@qepres.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 685301665

Inspection Date: 10/27/2016

FIR Submit Date: 10/31/2016

FIR Status: _____

Inspected Operator Information:

Company Name: QEP ENERGY COMPANY

Company Number: 10343

Address: 1050 17TH STREET - SUITE 800

City: DENVER State: CO Zip: 80265

LOCATION - Location ID: 313552

Location Name: CUTTHROAT-N37N19W Number: 10NENW County: MONTEZUMA

Qtrqr: NENW Sec: 10 Twp: 37N Range: 19W Meridian: N

Latitude: 37.484120 Longitude: -108.932590

FACILITY - API Number: 05-083-00 Facility ID: 224458

Facility Name: CUTTHROAT Number: 7

Qtrqr: NENW Sec: 10 Twp: 37N Range: 19W Meridian: N

Latitude: 37.484120 Longitude: -108.932590

CORRECTIVE ACTIONS:

1 ☒ CA# 53775

Corrective Action: Clean up stained soil to comply with Rule 906.a.

Date: 11/30/2016

Response: CA COMPLETED

Date of Completion: 12/07/2016

The stained soil at wellhead has been removed.

Operator
Comment:

COGCC Decision: Approved via an AMI

COGCC Representative: Photo documentation provided by Operator shows corrective action completed.

2 ☒ CA# 53776

Corrective Action: Remove pipe and fittings to comply with Rule 603.f using the Rule 603.f guidance document.

Date: 11/30/2016

Response: CA COMPLETED

Date of Completion: 12/07/2016

Operator
Comment: All excess equipment has been removed.

COGCC Decision: Approved via an AMI

COGCC Representative: Photo documentation provided by Operator shows corrective action completed.

3 ☒ CA# 53777

Corrective Action: Clean-up production area to comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 11/10/2016

Response: CA COMPLETED

Date of Completion: 12/07/2016

Operator
Comment: All excess equipment has been removed. Weeds have been removed.

COGCC Decision: Approved via an AMI

COGCC Representative: Photo documentation provided by Operator shows corrective action completed.

4 ☒ CA# 53778

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 11/30/2016

Response: CA COMPLETED

Date of Completion: 12/07/2016

Operator
Comment: Berms and ditches were repaired. 55 gallon drums were removed. Lease road was repaired.

COGCC Decision: Approved via an AMI

COGCC Representative: Photo documentation provided by Operator shows corrective action completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions were completed by December 7, 2016. Pictures are attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Stephanie Tomkinson

Signed: _____

Title: Sr. Biologist

Date: 12/12/2016 12:31:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401165199	FIR RESOLUTION SUBMITTED
401165219	CT7 Lease road entrance south of location
401165222	CT7 Lease road SE Canyon
401165239	CT7 Location
401165242	CT7 NE Corner berm repair
401165244	CT7 SE Corner berm repair

Total Attach: 6 Files