

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401182967
Date Received:
01/12/2017

FIR RESOLUTION FORM

CA Summary:
2 of 3 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Inspections, All		SanJuanCOGCC@bp.com
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685301955
Inspection Date: 12/12/2016 FIR Submit Date: 12/12/2016 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 312035

Location Name: SEMLER GAS UNIT A-N33N8W Number: 1SESW County: LA PLATA
Qtrqr: SESW Sec: 1 Twp: 33N Range: 8W Meridian: N
Latitude: 37.128605 Longitude: -107.671810

FACILITY - API Number: 05-067-00 Facility ID: 274149

Facility Name: SEMLER A Number: 2
Qtrqr: SESW Sec: 1 Twp: 33N Range: 8W Meridian: N
Latitude: 37.128605 Longitude: -107.671810

CORRECTIVE ACTIIONS:

1 CA# 54549

Corrective Action: Remove concrete block to comply with Rule 603.f using the Rule 603.f guidance document for further details. Date: 01/12/2017

Response: CA COMPLETED Date of Completion: 01/11/2017

Operator Comment: Concrete debris removed from location see attached closure document.

COGCC Decision: Approved

COGCC Representative: Photo documentation supplied by Operator shows corrective action completed.

3 CA# 54551

Corrective Action: Repair or install BMPs as required by Rule 1002.f. Refer to 1002.f guidance document for further details. Date: 01/12/2017

Response: CA COMPLETED Date of Completion: 01/11/2017

Operator Comment: Location graded, erosion repaired, wattles installed, and spot seeding performed to address storm water issues on location. See attached closure documentation

COGCC Decision: Approved

COGCC Representative: Photo documentation supplied by Operator show corrective action completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: New sign is on order and that CA will be closed when the sign is placed on location. Debris and stormwater CA's have been address please refer to closure documenation attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe Signed: _____

Title: Compliance Specialist Date: 1/12/2017 9:34:59 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401182967	FIR RESOLUTION SUBMITTED
401182976	Work Closure document Storm water and debris CA

Total Attach: 2 Files