

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401203415

Date Received:

02/06/2017

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

SanJuanCOGCC@bp.com

Beebe, Sabre

970-375-7530

Sabre.Beebe@bp.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 685302139

Inspection Date: 01/13/2017

FIR Submit Date: 01/13/2017

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 326245

Location Name: BLACK-M34N8W Number: 22NENW County: LA PLATA

Qtrqtr: NENW Sec: 22 Twp: 34N Range: 8W Meridian: M

Latitude: 37.181480 Longitude: -107.706128

### FACILITY - API Number: 05-067- -00 Facility ID: 216099

Facility Name: BLACK Number: 21-22 1

Qtrqtr: NENW Sec: 22 Twp: 34N Range: 8W Meridian: M

Latitude: 37.181480 Longitude: -107.706128

### CORRECTIVE ACTIONS:

1 ☒ CA# 60305

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 02/13/2017

Response: CA COMPLETED

Date of Completion: 01/31/2017

Operator Comment: BP has performed erosion repairs on this location in the form of installing wattles, installing rock run down, spot seeding and removing sediment from previously utilized BMP's. See attached documentation.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow Up Inspection to be conducted before 1/13/18.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: BP has performed erosion repairs on this location in the form of installing wattles, installing rock run down, spot seeding and removing sediment from previously utilized BMP's. See attached documentation.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 2/6/2017 4:15:53 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401203415	FIR RESOLUTION SUBMITTED
401203459	Work Completed documentation

Total Attach: 2 Files