

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401203510
Date Received:
02/06/2017

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Beebe, Sabre</u>	<u>970-375-7530</u>	<u>Sabre.Beebe@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 685301955
Inspection Date: 12/12/2016 FIR Submit Date: 12/12/2016 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 312035

Location Name: SEMLER GAS UNIT A- N33N8W Number: 1SESW County: LA PLATA
Qtrqr: SESW Sec: 1 Twp: 33N Range: 8W Meridian: N
Latitude: 37.128605 Longitude: -107.671810

FACILITY - API Number: 05-067-00 Facility ID: 274149

Facility Name: SEMLER A Number: 2
Qtrqr: SESW Sec: 1 Twp: 33N Range: 8W Meridian: N
Latitude: 37.128605 Longitude: -107.671810

CORRECTIVE ACTIIONS:

1 CA# 54549

Corrective Action: Remove concrete block to comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 01/12/2017

Response: CA COMPLETED

Date of Completion: 01/12/2017

Operator Comment: Please see FIRR document 401182967 for closure of this CA

COGCC Decision: Approved via an AMI

COGCC Representative: Photo documentation provided by Operator shows corrective action completed.

2 CA# 54550

Corrective Action: Install sign to comply with Rule 210.b Date: 02/11/2017

Response: CA COMPLETED Date of Completion: 02/06/2017

Operator Comment: Well Sign replaced on this location. See attached.

COGCC Decision: Approved via an AMI

COGCC Representative: Photo documentation provided by Operator shows corrective action completed.

3 CA# 54551

Corrective Action: Repair or install BMPs as required by Rule 1002.f. Refer to 1002.f guidance document for further details. Date: 01/12/2017

Response: CA COMPLETED Date of Completion: 01/12/2017

Operator Comment: Please see FIRR document 401182967 for closure of this CA

COGCC Decision: Approved via an AMI

COGCC Representative: Photo documentation provided by Operator shows corrective action completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: Well Sign replaced on this location. See attached.
Please see FIRR document 401182967 for closure of other CA

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe Signed: _____

Title: Compliance Specialist Date: 2/6/2017 4:46:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401203510	FIR RESOLUTION SUBMITTED
401203512	Sign Documentation
401203513	Sign Documentation

Total Attach: 3 Files