

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401213006

Date Received:

02/16/2017

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071

Name of Operator: BARRETT CORPORATION* BILL

Address: 1099 18TH ST STE 2300

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

COGCC_FIR@billbarrettcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682401734

Inspection Date: 01/26/2017

FIR Submit Date: 01/30/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BARRETT CORPORATION* BILL

Company Number: 10071

Address: 1099 18TH ST STE 2300

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 436885

Location Name: Ruh Number: 6-62-11_14 County: _____
NWNE

Qtrqtr: NWNE Sec: 11 Twp: 6N Range: 62W Meridian: 6

Latitude: 40.508175 Longitude: -104.286333

FACILITY - API Number: 05-123-

-00

Facility ID: 436885

Facility Name: Ruh Number: 6-62-11_14
NWNE

Qtrqtr: NWNE Sec: 11 Twp: 6N Range: 62W Meridian: 6

Latitude: 40.508175 Longitude: -104.286333

CORRECTIVE ACTIONS:

1 ☒ CA# 63451

Corrective Action: Compact berm to manage pollutant contributions to stormwater runoff from
unconsolidated soil material.

Date: 02/06/2017

Response: CA COMPLETED

Date of Completion: 02/06/2017

Operator
Comment:

Per field visit with Chris Binschus (COGCC) and Rusty Frishmuth (BBC), this is deemed complete.

COGCC Decision: Approved

COGCC
Representative:

BMP appears to be mostly wheel-packed.

Refer to the inspection photos taken on 2/15/17 in Document #682401804.

2  CA# 63452

Corrective Action: Replace or repair where equipment has damaged BMP and install BMP properly to ensure BMP properly functions.

Date: 02/06/2017

Response: CA COMPLETED

Date of Completion: 02/06/2017

Operator
Comment:

Completed

COGCC Decision: Approved

COGCC
Representative:

During the field visit on 2/15/17, COGCC staff and the Operator agreed the wattle BMP was repaired but has not been properly trenched and backfilled. Operator should complete the corrective action to properly install the wattle BMP.

Refer to the inspection photos taken on 2/15/17 in Document #682401804.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracey Fallang

Signed: _____

Title: Regulatory Manager

Date: 2/16/2017 4:41:34 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401213006	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files