

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/15/2017

Submitted Date:

02/17/2017

Document Number:

682401789**FIELD INSPECTION FORM**

Loc ID 445139	Inspector Name: Binschus, Chris	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>69175</u> Name of Operator: <u>PDC ENERGY INC</u> Address: <u>1775 SHERMAN STREET - STE 3000</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>				Findings: 9 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445132	WELL	XX	03/15/2016		123-42900	Cecil's Kersey Farm 17K-334	CI
445133	WELL	XX	03/15/2016		123-42901	Cecil's Kersey Farm 17K-204	CI
445134	WELL	XX	03/15/2016		123-42902	Cecil's Kersey Farm 17B-212	CI
445135	WELL	XX	03/15/2016		123-42903	Cecil's Kersey Farm 17K-402	CI
445136	WELL	XX	03/15/2016		123-42904	Cecil's Kersey Farm 17K-404	CI
445137	WELL	XX	03/15/2016		123-42905	Cecil's Kersey Farm 17K-332	CI
445138	WELL	XX	03/15/2016		123-42906	Cecil's Kersey Farm 17B-302	CI
445140	WELL	XX	03/15/2016		123-42907	Cecil's Kersey Farm 17K-232	CI
448415	WELL	XX	11/27/2016		123-43894	Cecils Kersey Farm 17B-304	CI
448416	WELL	XX	11/27/2016		123-43895	Cecils Kersey Farm 17B-214	CI

General Comment:

This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401190869. It should be noted the Operator was on location and communicated to COGCC staff there was an issue with stormwater BMPs, and already had plans to correct the described corrective actions.

Location Construction

Location ID: <u>445139</u>	CDP: _____
Comment: Topsoil salvaged, stored, and temporarily stabilized along the western and southern perimeter of location. Per Rule 1002, topsoil shall be stabilized and protected from degradation due to wind and water erosion. Per Rule 1002, BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.	
Corrective Action: _____	Date: _____

Form 2A COAs:**Comment:** An area of 13.94 acres was mapped on 2/15/2017 using a Trimble Juno 3B handheld device.

Corrective Action: _____

Date: _____**Wildlife BMPs:****Comment:** _____

Corrective Action: _____

Date: _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
DITCHES	Yes		

Comments: Erosion BMPs: Portions of the BMP have been damaged due to the sound wall installation and covered up by the stockpile along the northwest and western location. Also, a portion along the northwest location will have to be re-installed because the sound wall is being constructed on top of the BMP.

Other BMPs: _____

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 03/17/2017

BERMS	Yes		
-------	-----	--	--

Comments: Erosion BMPs: Portions of the BMP have been damaged due to the sound wall installation and covered up by the stockpile along the northwest and western location. Also, a portion along the northwest location will have to be re-installed because the sound wall is being constructed on top of the BMP.

Other BMPs: _____

Ensure all portions of the berm are properly compacted to manage pollutant contributions to stormwater runoff from unconsolidated soil material.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 03/17/2017

Comment: BMPs should remain in place and in proper functioning condition until the location reaches final reclamation.**Corrective Action:** _____**Date:** _____**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--	--

Inspected Facilities

Facility ID: <u>445132</u>	Type: <u>WELL</u>	API Number: <u>123-42900</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445133</u>	Type: <u>WELL</u>	API Number: <u>123-42901</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445134</u>	Type: <u>WELL</u>	API Number: <u>123-42902</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445135</u>	Type: <u>WELL</u>	API Number: <u>123-42903</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445136</u>	Type: <u>WELL</u>	API Number: <u>123-42904</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445137</u>	Type: <u>WELL</u>	API Number: <u>123-42905</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445138</u>	Type: <u>WELL</u>	API Number: <u>123-42906</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445140</u>	Type: <u>WELL</u>	API Number: <u>123-42907</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448415</u>	Type: <u>WELL</u>	API Number: <u>123-43894</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448416</u>	Type: <u>WELL</u>	API Number: <u>123-43895</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

COGCC Comments

Comment	User	Date
Appears additional disturbance was created from the sound wall installation along the southwestern location. Ensure that any additional disturbance is properly returned to the previous condition. Seedbed prep may need to be performed along portions of the cropland area.	binschusc	02/17/2017
Refer to attached inspection photos in Document #682401790.	binschusc	02/17/2017
When the Operator has completed the corrective actions, the Operator can take photo documentation and attach that documentation to the Field Inspection Report Resolution (FIRR) eForm. Please call with any questions on how to complete the FIRR process.	binschusc	02/17/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401213275	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4078347
682401790	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4078346