

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/17/2017

Submitted Date:

02/23/2017

Document Number:

674901502

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
326021 _____ Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 380 AIRPORT RD
 City: DURANGO State: CO Zip: 81303

Findings:

- 10 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215731	WELL	PR	08/03/2016	GW	067-07336	OPAL LECHNER A 1	EI

General Comment:

On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Opal Lechner A #1. For the most recent field inspection report of this facility, please refer to document #685300843.

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
	WELLHEAD		
Comment:	Stained soil around well head.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.		Date: <u>03/23/2017</u>
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Guard fencing and stock panel fencing.		
Corrective Action:			Date:
Equipment:			
Type: Vertical Heated Separator	# 1	corrective date	
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	SE marker was not found.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Not connected to well head at the time of this inspection.		
Corrective Action:			Date:
Venting:			

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 215731 Type: WELL API Number: 067-07336 Status: PR Insp. Status: EI**COGCC Comments**

Comment	User	Date
On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Opal Lechner A #1. For the most recent field inspection report of this facility, please refer to document #685300843.	hughesj	02/23/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401217711	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082738
674901503	Pump jack disconnected from well head.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082735
674901504	Free standing sign near location entrance.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082736
674901505	Impacted material around well head.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082737