



photo 1: Well sign at the location.



photo 2: There is a water leak which is iced over at the well head.



photo 3: Ice was noticed around the insulated piping.



photo 4: The fence around the pit is in disrepair.