

Inspected Facilities

Facility ID: 442304 Type: WELL API Number: 123-41789 Status: DG Insp. Status: WK

Complaint

Comment: Complaint DOC#2000441146.

OGCC inspector was on location on 3/7/17, wind speed were too high to investigate noise and odor issues. OGCC inspector will return to location on 3/8/17 to try and run a sound survey.

Corrective Action:

Date:

Well Stimulation

Stimulation Company: Liberty

Stimulation Type: HYDRAULIC FRAC

Other: _____

Observation:

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: Fluid: _____ Gas: _____

Comment: _____

Corrective Action: _____

Date: _____

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Vehicle Tracking	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT