

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2017

Submitted Date:

03/15/2017

Document Number:

678200636**FIELD INSPECTION FORM**

Loc ID 440990 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10311Name of Operator: SYNERGY RESOURCES CORPORATIONAddress: 1625 BROADWAY SUITE 300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pennington, David		dpennington@syrginfo.com	All Synergy Inspections
Axelson, John		john.axelson@state.co.us	

General Comment:

Environmental inspection of Spill Facility ID #449318.
 Contact area EPS (rob.young@state.co.us) by March 21, 2017 with a plan to address the oily mist impacted vegetation and soil to the north of CR 74.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678200642	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099428