



Severin Well Head

1 message

Meagan M. Miller <MMiller@bayswater.us>
To: "rick.allison@state.co.us" <rick.allison@state.co.us>

Fri, Mar 10, 2017 at 2:06 PM

Hi Rick –

I wanted to let you know about a historical release discovered today –

This is an old well – drilled in 1981 and abandoned without ever producing. It had surface casing set to 223'. It was drilled to 9320' and then abandoned without using very much cement/plugs to close off the well. As part of the drilling permits for the Thornton wells, a condition of approval was to re-enter and re-plug this well.

Mark Brown has had people out this week trying to find the old well. The surface casing was cut-off 4' below ground as is pretty normal. They had to do some digging around to locate the well since it was not located at the "precise" survey location footages as shown on all the well file info.

When they dug up the well today, the backhoe knocked off a very minimal cement cap while uncovering it and thus exposing the well. The casing was full of oil and there was some amount of old contaminated soil in parts of the trench. A roustabout crew manager indicated that he doesn't think that the contamination has spread out much.

At this point, our focus will be to do the work on the well to re-enter/re-plug it so as to eliminate any possibility of further contamination. Once that is accomplished, we will then determine the extent of the existing historic contamination and address it.

Please let me know if you have any questions. We will submit a Form 19 on Monday.

Thank you

Meagan

COGIS - WELL Information

Scout Card [Related](#) [Insp](#) [MIT](#) [GIS](#) [Doc](#) [COA](#) [Wellbore](#) [Orders](#)

Surface Location Data for API # 05-123-10461 Status: PA 11/19/1981

Well Name/No.: SEVERIN & CO #1 (click well name for production)

Operator: LECLAIR-WESTWOOD INC - 50560

Status Date: 11/19/1981 Federal or State Lease #: 407304

FacilityID: 242670 LocationID: NWSW 28 7N66W 6 PM

County: WELD #123 Location: 4,883 ft.

Field: WILDCAT - #99999 Elevation: 4,883 ft.

Planned Location: 1785 FSL 600 FWL Lat/Long: 40.543322/-104.790853 Lat/Long Calculated From Footages

Wellbore Data for Sidetrack #00 Status: AB 11/19/1981

Wellbore Permit

Permit #: 0 Expiration Date: 3/13/1982

Prop Depth/Form: Surface Mineral Owner Same:

Mineral Owner: FEE Surface Owner:

Unit: Unit Number:

Formation and Spacing: Code: UNK, Formation: UNKNOWN, Order: 0, Unit Acreage: 0, Drill Unit:

Wellbore Completed

Completion Date: 1/10/1982

Measured TD: 9320 Measured PB depth: 0

True Vertical TD: 0 True Vertical PB depth:

Formation	Log Top	Log Bottom	Cored	DSTs
Completed information for formation UNK Status: AB 11/19/1981				
1st Production Date:	N/A	Choke Size:	0.000	
Status Date:	11/19/1981	Open Hole Completion:		
Commingled:		Production Method:		
Formation Name:	UNKNOWN	Status:	AB	
Tubing Size:		Tubing Setting Depth:		
Tubing Packer Depth:		Tubing Multiple Packer:		
Open Hole Top:		Open Hole Bottom:		

No Mineral Lease Data was found for formation UNK.

Meagan M. Miller

Environmental Specialist



730 17th Street, Suite 610

Denver, CO 80202

Office: [303.893.2503](tel:303.893.2503) x204

Fax: [303.893.2508](tel:303.893.2508) – Attn: Meagan M Miller

Web: www.bayswater.us

Email: mmiller@bayswater.us

 **Severin Well Info.pdf**
114K