

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401201521  
Date Received:  
02/03/2017

FIR RESOLUTION FORM

CA Summary:  
4 of 4 CAs from the FIR responded to on this Form  
4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1625 BROADWAY STE 2200  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name Phone Email  
Tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 673803303  
Inspection Date: 06/10/2016 FIR Submit Date: 06/10/2016 FIR Status: SATISFACTORY w/ CMT or AR

Inspected Operator Information:

Company Name: PDC ENERGY INC Company Number: 69175  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 323675

Location Name: OCOMA B-65N64W Number: 29SWSW County: WELD  
Qtrqr: SWS Sec: 29 Twp: 5N Range: 64W Meridian: 6  
W  
Latitude: 40.364620 Longitude: -104.581590

FACILITY - API Number: 05-123-00 Facility ID: 323675

Facility Name: OCOMA B-65N64W Number: 29SWSW  
Qtrqr: SWS Sec: 29 Twp: 5N Range: 64W Meridian: 6  
W  
Latitude: 40.364620 Longitude: -104.581590

CORRECTIVE ACTIIONS:

1  CA# 50447

Corrective Action: Approx 5'x3' stained soil and oil in hole on south side of tank Repair leak and remove or remediate stained soil. "Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff." Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.

Date: 07/10/2016

Response: CA COMPLETED Date of Completion: 01/30/2017

Battery has been P&A'd

Operator  
Comment:

COGCC Decision: Approved

COGCC  
Representative:

2  CA# 50448

Corrective Action: "Location is within a designated setback location, install fencing per Rule 604.c. (2)M."

Date: 06/25/2016

Response: CA COMPLETED

Date of Completion: 01/30/2017

Operator  
Comment: Battery has been P&A'd

COGCC Decision: Approved

COGCC  
Representative:

3  CA# 50449

Corrective Action: Approx 5'x3' stained soil and oil in hole on south side of tank Repair leak and remove or remediate stained soil. "Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff." Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.

Date: 07/10/2016

Response: CA COMPLETED

Date of Completion: 01/30/2017

Operator  
Comment: Battery has been P&A'd

COGCC Decision: Approved

COGCC  
Representative:

4  CA# 50450

Corrective Action: SI

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 01/30/2017

Operator  
Comment: Battery has been P&A'd

COGCC Decision: Approved

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: \_\_\_\_\_

Title: EHS Tech

Date: 2/3/2017 9:40:01 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401201521	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files