

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401237951
Date Received:
03/20/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 26625
Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC
Address: 12225 GREENVILLE AVE STE 950
City: DALLAS State: TX Zip: 75243-9362

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net
Fischer, Alex		alex.fischer@state.co.us
Archuleta, Amy		aarchuleta@elmridge.net

COGCC INSPECTION SUMMARY:

FIR Document Number: 674901469
Inspection Date: 02/17/2017 FIR Submit Date: 02/21/2017 FIR Status:

Inspected Operator Information:

Company Name: ELM RIDGE EXPLORATION COMPANY LLC Company Number: 26625
Address: 12225 GREENVILLE AVE STE 950
City: DALLAS State: TX Zip: 75243-9362

LOCATION - Location ID: 325163

Location Name: FASSETT MESAVERDE UNIT- N33N8W Number: 7NENW County: LA PLATA
Qtrqtr: NENW Sec: 7 Twp: 33N Range: 8W Meridian: N
Latitude: 37.122850 Longitude: -107.762780

FACILITY - API Number: 05-067-00 Facility ID: 214173

Facility Name: FASSETT MESAVERDE UNIT Number: 1
Qtrqtr: NENW Sec: 7 Twp: 33N Range: 8W Meridian: N
Latitude: 37.122850 Longitude: -107.762780

CORRECTIVE ACTIIONS:

1 CA# 64889

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4). Date: 03/21/2017

Response: CA COMPLETED Date of Completion: 03/14/2017

Operator Comment: This location was too muddy to get a truck into pump out the secondary containment or to remove the produced water. We shut the well in on 2-16-17 to prevent any fluids from being produced and, as noted in the field inspection form, the location was too muddy and property owners were complaining about bringing the mud onto

the highway.. We had planned to fix the breach in the berm when the weather is suitable. We plan to fix this berm by 4-30-17. The berms have been fixed on this location as of 3-14-17.

COGCC Decision: Approved via an AMI

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amy Archuleta

Signed: _____

Title: Reg Supervisor

Date: 3/20/2017 3:28:43 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401237951	FIR RESOLUTION SUBMITTED
401237974	photo of location

Total Attach: 2 Files