

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/24/2017

Submitted Date:

03/21/2017

Document Number:

680601364**FIELD INSPECTION FORM**

Loc ID 333449 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre		Sabre.Beebe@bp.com	All Inspections
,		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278249	WELL	PR	08/10/2005	GW	067-09054	NEIL 34-13 2	RI
282625	WELL	PR	01/17/2006	GW	067-09100	NEIL 34-13 4	RI

General Comment:

[This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.](#)

Inspected Facilities									
Facility ID:	<u>278249</u>	Type:	<u>WELL</u>	API Number:	<u>067-09054</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>282625</u>	Type:	<u>WELL</u>	API Number:	<u>067-09100</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is fenced and surrounded by grassy pasture. Revegetation is sparse, but appears to be progressing within the interim reclamation area.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment Unused equipment is being stored within the southeastern portion of the project area.Corrective Action Removed unused equipment.Date **05/26/2017**

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: _____	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____	
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Overall Final Reclamation _____	Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Several erosional channels are eroding the eastern portion of the project area. See attached photos.](#)

Corrective Action: [Stormwater controls need to be installed to stabilize stormwater erosion within the project area.](#)

Date: 04/21/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680601365	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4104068