

Viertel 33-8-16 #3 FC
2 BBL Produced Water Spill
March 15, 2017



Figure 1. A well head packing leaked causing 2 bbl of CBM produced water to be released onto the location around the well head. This photograph was taken looking north east.



Figure 2. Spill area. Photograph taken looking south west.