

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/15/2017

Submitted Date:

03/20/2017

Document Number:

674300858**FIELD INSPECTION FORM**
 Loc ID 311832 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica		Jessica_Dooling@xtoenergy.com	Piceance Creek insp
Fischer, Alex		alex.fischer@state.co.us	
Lujan, Carlos		carlos.lujan@state.co.us	

General Comment:

Environmental**Spills/Releases:**Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: Followup to Spill #448284. Weather is warm and sunny. No activity at time of site visit but tackhoe is staged next to excavation. Spill area excavated to ~30'bgs into shale bedrock. No visible staining or odors from excavation. Excavated soils are stockpile withing berm to south of spill area. No apparent staing or odors in stockpile.

Corrective Action: Per COA, complete remediation until spill area complies with Table 910-1. Ether treat contaminated soil until Table 910-1 compliant or dispose of site a a licensed facility.

Date: 06/30/2017

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401237624	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102898
674300859	Spill area excavation looking southwest	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102891
674300860	Spile are excavation looking northwest	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102892
674300861	soil stockpile	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102893