

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/09/2017

Submitted Date:

03/27/2017

Document Number:

678200660**FIELD INSPECTION FORM**
 Loc ID 312292 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 518 17TH ST STE 200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Dale	719-688-1638	dale@westernoperating.com	
James, Steven	(303) 893-2438	steve@westernoperating.com	All Inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256303	PIT	AC			-	PROPST B-2	EI

General Comment:

Environmental inspection documenting erosion and vegetation kill related to produced water pit berm erosion. Oil skim culvert (tinhorn) requires closure under an approved Form 27.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 256303Lat: 40.896586Long: -103.269408

Reference Point: _____

Other: _____

Length: 160Width: 90**Lining:**

Liner Type:

Liner Condition:

Comment:

Substantial erosion from the south and west produced water pit berms has occurred. Vegetation needs to be restored.

Corrective Action

Submit a Form 27 for the remediation/reclamation of the affected areas.

Date: 04/14/2017c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

Type: Skimming/SettlingLined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Oil skim culvert.

Corrective Action

Submit a Form 27 describing the oil skim culvert (tinhorn) removal and confirmation soil sampling plan.

Date: 04/14/2017c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:				Date:
Corrective Action				
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:		Date:
Comment:				
Corrective Action				
Permit:	Facility ID	Permit Num	Expiration Date	
	256303	846025		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678200661	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110286
678200662	Google Earth aerial showing salt kill outline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110287