

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/14/2017

Submitted Date:

03/28/2017

Document Number:

680601383

FIELD INSPECTION FORM

Loc ID 320878 Inspector Name: ROY, CATHERINE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10559
Name of Operator: SOUTHLAND ROYALTY COMPANY LLC
Address: 400 WEST 7TH STREET
City: FORT WORTH State: TX Zip: 76102

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Hampton, John	505-330-4377	jhampton@ctfieldsvcs.com	SW Inspections
Semlar, Willard	505-330-4302	wsemmler@ctfieldsvcs.com	SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265863	WELL	PR	03/08/2013	GW	007-06196	DUNGAN 32-5 5-1	RI
374711	WELL	PR	06/11/2009	GW	007-06279	CANDELARIA 32-5 8-3	RI

General Comment:

This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.

Inspected Facilities

Facility ID: 265863 Type: WELL API Number: 007-06196 Status: PR Insp. Status: RI

Facility ID: 374711 Type: WELL API Number: 007-06279 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by pinion juniper woodland. Revegetation is progressing within the interim reclamation areas. See attached photos.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment

Corrective Action

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment

Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment

Corrective Action

Date _____

1003a. Waste and Debris removed? _____

Comment

Corrective Action

Date _____

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment

Corrective Action

Date _____

Guy line anchors marked? _____

Comment

Corrective Action

Date _____

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater rilling is occurring and an erosional channel is forming in the southern and southwestern portions of the project area. Perimeter wattles are largely full of sediment.

Corrective Action: Stormwater controls need to be installed to stabilize stormwater erosion and wattles need maintenance.

Date: 04/30/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680601384	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110292