

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2017

Submitted Date:

03/31/2017

Document Number:

669600039

FIELD INSPECTION FORM

Loc ID 326245 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216099	WELL	PR	05/03/2005	GW	067-07705	BLACK 21-22 1	PR

General Comment:

[See link at end of report for path to downloadable pictures.](#)

Inspected Facilities

Facility ID: 216099 Type: WELL API Number: 067-07705 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Pass	Gravel	Pass			
Rip Rap	Pass					
Gravel	Pass					
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Spill prevention under lube oil tank.
Waddles	Pass					

Comment: [Corrective action completed.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
669600149	Erosion channel repair and reseeded area.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114264
669600150	Erosion channel repair.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114265
669600152	Spill prevention under lube oil tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114266