



photo 1: There is sediment migration onto the access road.



photo 2: Well sign.



photo 3: Facing toward the west side of the location. There are signs of stormwater run on which is depositing sediment onto the location.



photo 4: Facing toward the pit. Did not notice a freeboard marker.