

From: [Tran, Samantha](#)
To: diana.burn@state.co.us
Cc: [Light, Cheryl](#); [Green, Doreen](#); [Pitts, Bob](#)
Subject: Update on HSR FULENWIDER 10-21
Date: Monday, February 27, 2017 4:42:21 PM
Attachments: [image003.png](#)

Hi Diana,

We are currently on the **HSR FULENWIDER 10-21 (API#05-001-09331)**. As discussed on the phone, we attempted to pump the susx squeeze cement job but began pressuring up to over 1800 psi. We agreed that since the surrounding wells within 1 mile of the HSR FULENWIDER 10-21 has no SUSX/SH production, we will pump whatever we can under the CICR and at least 2 sx of cement on top. Unfortunately, we were unable to pump anything below the CICR and ended up pumping 3 sx of cement on top of the CICR.

Thank you,
Samantha

--

Samantha Tran
Field Production Engineer I



501 North Division Blvd
Platteville, CO 80651
(970) 515 – 1571 Direct
(832) 540 – 0209 Cell