

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2017

Submitted Date:

04/06/2017

Document Number:

680601413

**FIELD INSPECTION FORM**

Loc ID 326097 Inspector Name: ROY, CATHERINE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 30680  
Name of Operator: FOUR STAR OIL & GAS COMPANY  
Address: 6301 DEAUVILLE BLVD  
City: MIDLAND State: TX Zip: 79706

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Pohl, April	505-333-1941	april.pohl@chevron.com	<a href="#">All Inspections Southwest</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215861	WELL	PR	07/08/1993	GW	067-07466	STATE 36-2	RI

**General Comment:**

*This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.*

**Inspected Facilities**

Facility ID: 215861 Type: WELL API Number: 067-07466 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by pinion juniper woodland. Revegetation is progressing within portions of the interim reclamation area.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment

Corrective Action

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1003b. Area no longer in use?      In      Production areas stabilized ?       
 1003c. Compacted areas have been cross ripped?       
 1003d. Drilling pit closed?      Subsidence over on drill pit?       
 Cuttings management:       
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?       
 Production areas have been stabilized?      Segregated soils have been replaced?     

RESTORATION AND REVEGETATION

Cropland

Top soil replaced      Recontoured      Perennial forage re-established     

Non-Cropland

Top soil replaced      Recontoured      80% Revegetation     

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA%       
 TRANSECT RESULTS OF REFERENCE AREA%       
 TOTAL % OF DESIRABLE VEGETATION COVER       
 VEGETATIVE COVER     

1003 f. Weeds Noxious weeds?     

Comment An area in the eastern portion of the project area has poor vegetative cover and is eroding.

Corrective Action Eroding area with poor vegetative cover needs to be re-seeded within the spring planting window but no later than June 1, 2017. Mulching at the time of seeding is recommended

Date 06/01/2017

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started:      Date Final Reclamation Completed:     

Final Land Use:     

Reminder:     

Comment:     

Well plugged      Pit mouse/rat holes, cellars backfilled     

Debris removed      No disturbance /Location never built     

Access Roads Regraded      Contoured      Culverts removed     

Gravel removed     

Location and associated production facilities reclaimed      Locations, facilities, roads, recontoured     

Compaction alleviation      Dust and erosion control     

Non cropland: Revegetated 80%      Cropland: perennial forage     

Weeds present      Subsidence     

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA%       
 TRANSECT RESULTS OF REFERENCE AREA%       
 TOTAL % OF DESIRABLE VEGETATION COVER       
 VEGETATIVE COVER     

Comment:     

Corrective Action:     

Date     

Overall Final Reclamation      Well Release on Active Location  Multi-Well Location

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Stormwater erosion is occurring in the eastern portion of the project area. Wattles are largely not functioning. Cobble run-downs and silt traps appear to be functioning at this time. See attached photos.</p> <p>Corrective Action: Stormwater controls need to be maintained or replaced to stabilize erosion in the eastern portion of the project area. Revegetation as described in the reclamation section should help stabilize this area for the long-term.</p>						Date: 05/12/2017
<p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680601414	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117395">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117395</a>